



Printer Firmware Release Notes

Second Generation Commercial Printers v10.11.0

Overview

Printer firmware version 10 provides printing and other functions for Intermecc by Honeywell second-generation printers.

Supported Printers

This firmware supports the following printers:

Family	Model Names	Firmware Code
Commercial	PD41, PD42	10.x.x

Notes:

16MB SDRAM is required to upgrade to this firmware version.

This firmware requires a boot loader version newer than 13 July 2009.

Please refer to the online help or the printer user manual for additional information on the features and use of the printer firmware and your printers.

This version at-a-glance

- Compliance with European EN300328 Standard v1.81
- Add ^r Reset and ^q Query commands in bi-directional protocol in Fingerprint
- Resolved an issue with human-readable text not printing with EAN13 bar codes in Fingerprint
- Resolved an issue with ZSim “freezing”

Version 10.11.0 Key Features

New Functionality

EU EN300328 Standard v1.81 Compliance

This firmware makes printers compliant with this new European Union standard for WiFi radios.

Add new commands to Fingerprint bi-directional protocols

Added two new commands to the Fingerprint bi-directional protocol

^q – Query

^r – Reset

Changed Functionality

CPR 140120=000027: EAN13 Human-readable text not visible

This is now fixed.

iFAST 140204-000032 – ZSim freezes on some layouts

This is now fixed.