CK60 Handheld Computer Scan Handle



Intermec

Instructions

Instructions

The Intermec CK60 Handheld Computer Scan Handle kit (p/n: 805-633-001) allows for easily attaching a Scan Handle accessory. The Scan Handle also provides for an optional wrist strap to be attached. The Scan Handle s designed for better ergonomics for higher-volume scanning applications. The Scan Handle provides a trigger to activate reading the bar code.
NOTE: The illustration shows the hand strap already removed.

1 Remove the hand strap by unlatching the bottom strap latch and turning the upper turn buckle a quarter turn clockwise.

2 Lift the Scan Handle Turn Buckles (top and bottom buckles), turn buckles counterclockwise to position into retaining sockets.

3 Turn buckles clockwise a quarter turn and press buckles down to secure into place.

4 Attach optional wrist strap to strap pin.

CK60 Scan Handle Instructions

P/N 943-001-001

Intermec
Corporate Headquarters
6001 36th Avenue West
Everett, Washington 98203 U.S.A.
tel 425.348.2600
www.intermec.com
© 2005 Intermec Technologies Corporation. All rights reserved.

CK60 Handheld Computer Scan Handle



Intermec

Instructions

Instructions

The Intermec CK60 Handheld Computer Scan Handle kit (p/n: 805-633-001) allows for easily attaching a Scan Handle accessory. The Scan Handle also provides for an optional wrist strap to be attached. The Scan Handle s designed for better ergonomics for higher-volume scanning applications. The Scan Handle provides a trigger to activate reading the bar code.
NOTE: The illustration shows the hand strap already removed.

1 Remove the hand strap by unlatching the bottom strap latch and turning the upper turn buckle a quarter turn clockwise.

2 Lift the Scan Handle Turn Buckles (top and bottom buckles), turn buckles counterclockwise to position into retaining sockets.

3 Turn buckles clockwise a quarter turn and press buckles down to secure into place.

4 Attach optional wrist strap to strap pin.

CK60 Scan Handle Instructions

P/N 943-001-001

Intermec
Corporate Headquarters
6001 36th Avenue West
Everett, Washington 98203 U.S.A.
tel 425.348.2600
www.intermec.com
© 2005 Intermec Technologies Corporation. All rights reserved.

CK60 Handheld Computer Scan Handle



Intermec

Instructions

Instructions

The Intermec CK60 Handheld Computer Scan Handle kit (p/n: 805-633-001) allows for easily attaching a Scan Handle accessory. The Scan Handle also provides for an optional wrist strap to be attached. The Scan Handle s designed for better ergonomics for higher-volume scanning applications. The Scan Handle provides a trigger to activate reading the bar code.
NOTE: The illustration shows the hand strap already removed.

1 Remove the hand strap by unlatching the bottom strap latch and turning the upper turn buckle a quarter turn clockwise.

2 Lift the Scan Handle Turn Buckles (top and bottom buckles), turn buckles counterclockwise to position into retaining sockets.

3 Turn buckles clockwise a quarter turn and press buckles down to secure into place.

4 Attach optional wrist strap to strap pin.

CK60 Scan Handle Instructions

P/N 943-001-001

Intermec
Corporate Headquarters
6001 36th Avenue West
Everett, Washington 98203 U.S.A.
tel 425.348.2600
www.intermec.com
© 2005 Intermec Technologies Corporation. All rights reserved.