

# Software Release Notes

## Software Release Notes

### CN51 OS v1.30

### China WWAN Release

Android™ - 4.2.2 (Jelly Bean)

## Overview

This is an OS release build of Android 4.2.2 (Jelly Bean) for the CN51 mobile computer that meets requirements specific to WWAN-only devices marketed in China. Supported devices have the value of "0C" in the 10<sup>th</sup> and 11<sup>th</sup> positions of the configuration number. Use of this build on other device configurations is not supported and may result in inoperable devices.

## Supported Hardware

All CN51 WLAN-only configurations for China delivered with Android 4.2.2.

## Version numbers

	<b>1.30 Release</b>
Build number(s)	1.30.02.58
Android version	4.2.2
Baseband version	03.001
Battery Swap	1.0
BatteryInfo	1.0
Bug Reporter	1.0.3
Hardware Verify	1.0
Carrier Selection	1.7.0
Configuration Service	1.20.00.94
Print Service	1.20.00.181
Scan Demo	1.30.02.0016
Scanners	1.30.02.0016
ScanNGo	1.10.0.00.55

## **CN51 Android Release 1.30 New Features**

1. Fix issue where devices hang on boot after factory reset.
2. Introduction of WLAN (802.11 abgn supported radio) only CN51 configurations for China.
3. Introduction of “No camera” CN51 configurations.
4. Wi-Fi and CCX Certifications.
5. Improved connection and roaming support for non-Cisco WLAN AP infrastructure.
6. OpenSSL Security Library fix for the Heartbleed issue.

## **CN51 Android Procedures**

### **Android OS Update via System Menus**

Update will be available as a download from Intermec.com

1. Copy the software update file to the internal storage, or to an installed microSD card. The update file can also be copied to a microSD card and then inserted into the CN51.
2. Start the Settings app, and tap “About phone” > “System updates”.
3. Tap the file name and then tap “OK”. The update begins and may take several minutes. When the update is complete, the computer will restart.

### **Factory Reset Instructions**

1. Open the Settings menu and select “Backup & reset” > “Factory data Reset”.
2. Tap “Reset phone”. A confirming message appears, reminding you that you cannot reverse this action.
3. Tap “Erase everything”. The computer restarts and all user data, files, and downloaded apps are erased.

## Additional Information

The CN51 handheld computer manual and downloads are located at:

[www.intermec.com](http://www.intermec.com) | Products | Computers | Handheld Computers | CN51

### Support Assistance

For product assistance or to report an issue/observation, contact Technical Support by calling 1-800-755-5505 then option 4, 2. Outside North America, contact your normal support persons and they will enter a Knowledge Central case. If you would like to submit an online case, follow this link: <http://intermec.custhelp.com/app/ask> If you don't have an account, one can be created via the link on the right hand side.

### Intermec USB Driver

This driver is needed to be able to USB Tether, Android Debug Bridge (ADB), and use the device as an MTP device (this enables file exploring from a XP/7 computer). Visit <http://www.intermec.com/support/downloads/> to get the released version. It is also delivered in the Intermec Developer Libraries.

For more information about ADB, visit: <http://developer.android.com/tools/help/adb.html>.

For more information about USB Tethering, please see the latest CN51 Android User Guide. Available at: <http://www.intermec.com/support/downloads/>

### Application Support

#### Printing SDK v1.0

Available by Intermec Developer Libraries or at <http://www.intermec.com/support/downloads/>

#### Data Collection SDK v1.0

Available by Intermec Developer Libraries or at <http://www.intermec.com/support/downloads/>

#### ScanNGo Barcode Generator

Visit <http://www.intermec.com/support/downloads/> to get the released version.

#### Intermec Developer Libraries

The Intermec SDKs are available through the Android SDK Manager.


1. Download and install the Android SDK
2. Open the Android SDK Manager
3. Navigate to "Tools" > "User Defined Sites" > "New..."
4. Enter the following URL: **<http://sdk.android.intermec.com:60093/sdk/addon.xml>**
5. Click "OK", and then close the Add-on Sites menu.
6. Navigate to the Extras Folder, and expand it.
7. Click the checkbox next to the desired SDKs and then click Install.
8. The Intermec SDKs will be downloaded to the Android SDK folder extras directory.

### Best Practices

1) When using the camera in a custom application it is important to use the “setDisplayOrientation” method provided by the Android SDK. Please see following link for more details.

[http://developer.android.com/reference/android/hardware/Camera.html#setDisplayOrientation\(int\)](http://developer.android.com/reference/android/hardware/Camera.html#setDisplayOrientation(int))

2) For even better roaming support on non-Cisco infrastructure, Disable power save mode (CAM). This can be done by opening the Wi-Fi menus, clicking advanced settings (A), and setting “Wi-Fi power save mode allowed” to “Disabled”.



3) Computers with XP operating system will need Media Player 10 and the Intermec USB driver to connect to a CN51 Android device.

4) Manually reboot the device after the Sprint OMADM Activation process completes. The data connection may not function without a reboot.

## Version History

<b>Version</b>	<b>Date Available</b>
1.30.02.58 – WWAN CHINA	March 2015