


Trakker Antares 241X Cable Instructions


To install the cable

1. Insert the cable connector into the integrated I/O connector on the terminal.
2. Slide the metal locking bracket toward the terminal to lock the cable connector to the terminal.



To remove the cable

1. Slide the metal locking bracket away from the terminal to release the cable connector.
2. While pressing both tabs, disengage the cable connector from the integrated I/O connector.



Part No. 070193-001



070193-001

Intermec
Technologies Corporation

6001 36th Avenue West
P.O. Box 4280
Everett, WA 98203-9280

© 1999 Intermec
All Rights Reserved