

**SOFTWARE RELEASE NOTES**  
**For**  
**CN30 WM5**  
**Version**  
**3.10.10.0022**

1. Purpose	3
1.1. Purpose of this Release	3
2. Configuration Identification	3
2.1. Hardware Platform	3
2.2. OS Platform	3
3. Software Files	4
3.1. Displayed Version Numbers	4
3.2. Software Build Replacement Information	4
4. New Functionality Added	4
4.1. Platform	4
4.2. SSPB	4
5. Defects Fixed In This Build	<b>Error! Bookmark not defined.</b>
5.1. Platform	<b>Error! Bookmark not defined.</b>
5.2. SSPB	<b>Error! Bookmark not defined.</b>
6. Other information	4
6.1. Installation Instructions	5
7. Errata	6

# CN30 Release Notes

## 1. Purpose

This document provides information regarding the latest CN30 Windows Mobile 5 software release.

### 1.1. Purpose of this Release

The purpose of this release is:

- To support the release of the CN30 ROHS model.

## 2. Configuration Identification

This software release was tested against:

SmartSystems Console: 3.11.01.0094

Avalanche Console: 3.6.3

### 2.1. Hardware Platform

This software release is intended to run on CN30B terminals.

CN30A are not supported

### 2.2. OS Platform

Windows Mobile 5.0 Premium Edition

### 3. Software Files

Software is available for download on the Intermec downloads website

[http://home.intermec.com/eprise/main/GSS/Service/Content/Downloads/Show\\_DownloadSearchResults?Product=CMPTRCN30A](http://home.intermec.com/eprise/main/GSS/Service/Content/Downloads/Show_DownloadSearchResults?Product=CMPTRCN30A)

#### 3.1. Displayed Version Numbers

Component	Current Version
OS	3.10.10.0022
SSPB (SmartSystems Platform Bundle)	5.00.07.0178

SSPB Components (SmartSystems Platform Bundle)	Current Version
Wavelink Enabler	3.50-51
Funk Supplicant	2.01.00.214
SSRef Client	3.01.01.0042
IVA	5.00.42.1435
802.11 Driver	1.0.0.46

#### 3.2. Software Build Replacement Information

	Release	Date Available
<b>Initial Release:</b>	3.10.10.0022 5.00.07.0178	6/11/2007

### 4. New Functionality Added

#### 4.1. Platform

- This release is for **CN30B ONLY**. (ROHS)
- Microsoft AKU 3.0

#### 4.2. SSPB

- None

### 5. Other information

Please reference the CN30 Handheld Computer User's Manual for additional information.  
[www.intermec.com](http://www.intermec.com) | Service & Support | Manuals

## **5.1. Installation Instructions**

The operating system and SSPB can be reinstalled via SD Card or SmartSystems, for installation instructions refer to the readme contained inside the OS exe.

## 6. Errata

ID	Description Summary	Systems
22308	Installselect will not function properly when the SSPB is installed from the SSSconsole. Any modifications to what is or is not to be installed should be made on the console prior to deployment.	Install Select
22905	Intermec settings-PDF417 is not enabled by default.	Intermec Settings
22877	The computer may need to be reset after unexpected power loss or battery removal.	Wireless Radio
22764	If a Smartsystems backup fails to complete the device must be rebooted before trying again.	Smart Systems
22656	The Bluetooth control panel applet should be used to manage BT power.	Bluetooth
22862	The “add to favorites” option in Intermec settings is not fully implemented and will cause an error requiring a reboot to correct if used.	Intermec Settings
22202	All power management options may not display in Intermec Settings until the user performs one reboot.	Intermec Settings
21900	Avalanche packages must be created from a backup settings file and can not be created directly from the SSPB console install.	Avalanche
18671	Avalanche packages have the 802.11 radio disabled by default, ensure that is changed prior to deploying settings if 802.11 connectivity is needed.	Avalanche