

SOFTWARE RELEASE NOTES  
For  
CV60  
Version  
**2.01.00.0151 CE**

1. Purpose	3
1.1. Purpose of this Release	3
2. Configuration Identification	3
2.1. Hardware Platform	3
2.2. OS Platform	3
3. Software Files	3
3.1. Displayed Version Numbers	3
3.2. Software Build Replacement Information	3
4. New Functionality Added	4
5. Defects Fixed In This Build	4
6. Other information	4
6.1. Installation Instructions	4
7. Errata	5

# CV60 Release Notes

## 1. Purpose

This document provides information regarding the latest CV60 software release.

### 1.1. Purpose of this Release

The purpose of this release is:

- To support the release of the a/b/g radio on the CV60 Windows CE .NET 4.2 operating system.

## 2. Configuration Identification

This software release was tested against:

SmartSystems Console: 3.11.01.0094

Avalanche Console: 3.6.3

### 2.1. Hardware Platform

This software release is intended to run on CV60 terminals.

### 2.2. OS Platform

Windows CE .NET 4.2

## 3. Software Files

Software is available for download on the Intermec downloads website

[http://home.intermec.com/eprise/main/GSS/Service/Content/Downloads/Show\\_DownloadSearchResults?Product=CMPTRCV60](http://home.intermec.com/eprise/main/GSS/Service/Content/Downloads/Show_DownloadSearchResults?Product=CMPTRCV60)

### 3.1. Displayed Version Numbers

Component	Current Version
OS	2.01.00.0151
SSPB (SmartSystems Platform Bundle)	Built-In

SSPB Components (SmartSystems Platform Bundle)	Current Version
Wavelink Enabler	4.02-01
Funk Supplicant	2.01.00.0237
IVA	4.03.38.1216
DHCP Client	1.01.14

### 3.2. Software Build Replacement Information

	Release	Date Available
<b>Win CE 5.0</b>	2.01.00.0151	2/14/2007

#### **4. New Functionality Added**

- Support for the Broadcom a/b/g 802.11 radio.
- New avalanche enabler from wavelink - Avalanche will now install after the pen calibration on the first boot.

#### **5. Defects Fixed In This Build**

- None

#### **6. Other information**

Please reference the CV60 Handheld Computer User's Manual for additional information.  
[www.intermec.com](http://www.intermec.com) | Service & Support | Manuals

##### **6.1. Installation Instructions**

For installation instructions refer to the Recovery CD.

## 7. Errata

ID	Description Summary	Systems
23638	A low density roaming profile needs to be used if the device seems to thrash between access points.	Wireless Radio
23616	Properties App from Infrastructure Mode in Intermec Settings is not supported.	Intermec Settings
23569	Using 802.11 Config to import certificates is not supported. Use Intermec Settings.	802.11 Config
13544	By default the screen taps under Volume and Sounds properties is enabled but currently this feature is not supported.	Audio
12779	1552 - Does not support 'fixed length' barcodes for I2 of 5.	Data Collection
12778	1552 – Does not support Code 11 decode length of < 6.	Data Collection
12708	1552 – Does not support setting <disable> Start/Stop Transmitted.	Data Collection
12059	SmartSystems does not support backup of PSK settings.	Smart Systems
5918	1552 – Does not support Code 11, one digit (2 chars) barcode if set Length to 2.	Data Collection