

SOFTWARE RELEASE NOTES
For
IF30
Version
1.31-1.61-Aug-16-2010

1.	Configuration Identification	3
2.	Hardware Platform	3
3.	Software Files.....	3
3.1.	Displayed Version Numbers	3
3.2.	Software Build Replacement Information	3
4.	Known External Compatibility Issues.....	3
5.	New Functionality Added	3
5.1.	Platform	3
5.2.	IM5	3
6.	Defects Fixed In This Build	3
6.1.	Platform	3
6.2.	IM5	3
7.	Other information.....	5
8.	Errata	5

IF30 Release Notes

1. Configuration Identification

This software release was tested against:
Avalanche Console: 3.6.3

2. Hardware Platform

This software release, version 1.31, is a follow-on software release to support the IF30 hardware. It will run on all currently available IF30A hardware, as well as the newly-available IF30B hardware.

Note: IF30A hardware that is installed with version 1.10 must first be upgraded to version 1.30 before upgrading to this version. Version 1.30 is not compatible with IF30B hardware.

DO NOT LOAD VERSION 1.30 in IF30B HARDWARE.

3. Software Files

3.1. Displayed Version Numbers

Component	Current Version	Previous Version
IF30 System	1.31-1.61-Aug-16-2010	1.30-1.60-Dec-14-2009
IM5 Module Application	10.16	10.16
IM5 Module Bootloader	2.26	2.14

3.2. Software Build Replacement Information

	Release	Date Available
Initial Release	1.00-1.20-Jan-12-2007	01/12/2007
1.10 Release	1.10-1.28-Aug-02-2007	08/16/2007
1.31 Release	1.30-1.60-Dec-14-2009	12/14/2009
1.32 Release	1.31-1.61-Aug-16-2010	12/10/2010

4. Known External Compatibility Issues

None

5. New Functionality Added

5.1. Platform

None

5.2. IM5

Added new bootloader (2.26) to support IM5R3 modules

6. Defects Fixed In This Build

6.1. Platform

None.

6.2. IM5

None.

7. Other information

Please reference the IF30 User's Manual for additional information.
www.intermec.com | Service & Support | Manuals

8. Errata

None